



Emergency Levee Repairs Fall 2006

Location

River: Butte Creek

River Mile: 14.0

Longitude/Latitude:

N39.684507

W121.778462

Nearest City: Chico

County: Butte

Bank: Right

Length of Repair

1,100 feet (approximate)*

Repair Type

Riprap (rock armor) with
woody material, vegetation
plantings, and cobble material

Lead Agency

Department of Water Resources

* Length of repair may change.

**For further information,
please contact:**

Elizabeth Scott
DWR Public Affairs Office
(916) 835-5344
leveerepair@water.ca.gov

DEPARTMENT OF WATER RESOURCES
PO Box 942836, Sacramento, CA 94236

www.levees.water.ca.gov

